
Preliminary Hand- Held Air Monitoring Locations | ITC Deer Park Tank Fire

Reading Date

3/28/2019 12:00:00 PM to 3/28/2019 1:00:00 PM



Recent Benzene Detections

Division E	3/28/2019 12:59:08	0.700
		0.700 ppm
	3/28/2019 12:53:06	1.825 ppm
	3/28/2019 12:52:25	2.470 ppm
	3/28/2019 12:50:39	0.180 ppm
	3/28/2019 12:47:37	0.150 ppm
	3/28/2019 12:44:50	0.140 ppm
	3/28/2019 12:44:37	1.390 ppm
	3/28/2019 12:39:45	0.580 ppm
	3/28/2019 12:30:59	1.130 ppm
	3/28/2019 12:30:04	7.360 ppm
	3/28/2019 12:24:53	0.350 ppm
	3/28/2019 12:23:37	0.050 ppm
	3/28/2019 12:21:42	0.110 ppm
	3/28/2019 12:14:59	3.625 ppm
	3/28/2019 12:14:12	0.840 ppm
	3/28/2019 12:11:02	0.250 ppm
	3/28/2019 12:10:42	4.675 ppm
	3/28/2019 12:05:56	0.280 ppm
	3/28/2019 12:03:26	0.325 ppm
Impacted Tank Farm	3/28/2019 12:52:41	0.920 ppm
	3/28/2019 12:52:06	1.330 ppm
	3/28/2019 12:14:12	0.170 ppm
Industrial Area	3/28/2019 12:57:58	0.910 ppm
	3/28/2019 12:48:48	1.475 ppm

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis. It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only